~User:

Wednesday, 06/09/2006 11:05:37 AM

Linda Lacelle

Process Sheet

Customer Job Number Estimate Number P.O. Number This Issue Prsht Rev. First Issue Previous Run

: CU-DAR001 Dart Helicopters Services

: 28427

: 12525 : NA

: 06/09/2006

S.O. No. : NA

Written By

Checked & Approved By

Comment

: SMALL /MED FAB

: Est Rev:A New Issue 06-09-08 EC

Drawing Name

Part Number Drawing Number

Project Number Drawing Revision

Material **Due Date**

: UNDER REVIEW

: N/A

: 13/09/2006

E 06.09.05

Each

(4)

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

D35311--1.0

Comment: Qty.:

1.0000 Each(s)/Unit

Total: 2.0000 Each(s)

BRACKET

D35313 --

BRACKET

07-03.08

Comment: Qty.:

1.0000 Each(s)/Unit

2.0000 Each(s) Total:

BRACKET FRONT PLATE MS20470AD44.J

CB 07.03,08

3.0

Comment: Qty.: 12.0000 Each(s)/Unit

Total:

24.0000 Each(s)

Rivet, Universal Head

4.0

2.0

SMALL & MEDIUM FAB RESOURCE 1

Comment: SMALL & MEDIUM FAB RESOURCE 1

Assemble as per dwg D3531

5.0

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

POWDER COATING

Comment: POWDER COATING

Powder Coat Black Sandtex (Ref: 4.3.5.7) as per QSI 005 4.3

rospac	e Ltd							
		٧	VORK ORDER CHANGES				-	
STEP	PROC	EDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							;	,-
			,					
:	PAR #:	Fault Ca	tegory: NC	~				
	W	ORK OR	DER NON-CONFORMANCE	(NCR)				
	Description of NC		Corrective Action Section B		Verific:	ation	Annroval	Approval
STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date			Chief Eng	QC Inspector
						•		
	STEP	:PAR #:W(STEP PROCEDURE CHECK PAR #: Fault Ca WORK OR STEP Description of NC Section A Initial	WORK ORDER CHANGES STEP PROCEDURE CHANGE :PAR #:Fault Category:NC WORK ORDER NON-CONFORMANCE WORK ORDER NON-CONFORMANCE STEP Description of NC	WORK ORDER CHANGES STEP PROCEDURE CHANGE By PAR #: Fault Category: NCR: Yes \(\) QA: N/O WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC	WORK ORDER CHANGES STEP PROCEDURE CHANGE By Date :PAR #:Fault Category:NCR: Yes_NO_DQA QA: N/C Closed WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC Section A Initial Action Description Sign & Section B Veriffic Section Section B Sign & Section B Sign & Section	WORK ORDER CHANGES STEP PROCEDURE CHANGE By Date Qty :PAR #:Fault Category:NCR: Yes No DQA: QA: N/C Closed: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC	WORK ORDER CHANGES STEP PROCEDURE CHANGE By Date Qty Chief Eng / Prod Mgr : PAR #: Fault Category: NCR: Yes No DQA: Date: QA: N/C Closed: Date: QA: N/C Closed: Date: Step Description of NC Section A Section C Section C Chief Eng Date: Chief Eng Date: QA: N/C Closed: NCR: Yes No DQA: Date: QA: N/C Closed:

NOTE: Date & initial all entries

Date: Wednesday, 06/09/2006 11:05:38 AM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: BRACKET ASS'Y Job Number: 28427 Part Number: D3531041 Job Number: Seq. #: Description: **Machine Or Operation:** 7.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERSION Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION PACKAGING RESOURCE# 8.0 PACKAGING 1 Comment: PACKAGING RESOURCE #1 Identify and Oteck Ion end use Location: 9.0 FINAL INSPECTION/W/O RELEASE Comment: Inspection Level 21 Job Completion O Eng Approval · CB.07.03.08 PART WENT TO HAI. PART NOT APPROVED AND NOT AIRWORTHY CB 07.07.13


Dart Ae	rospace	e Lta								
W/O:			W	ORK ORDER CH	ANGES					
DATE	STEP	PR	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					*					
			6							
Part No	:	PAR #:	Fault Cat	egory:	NCI	R: Yes	No DQ	A:	Date:	
						QA: N	C Close	d:	_ Date: _	
NCR:		1	WORK ORI	DER NON-CONFO	RMANCE	(NCR)			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Action Descript	Section B	Sign &	Verific Section		Approval Chief Eng	Approval QC Inspector
		·		Onto Ling					***	
								1		
(4)									10	
		a.			į					·
										15


NOTE: Date & initial all entries


PRELIMINARY ISSUE


	C By	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CA	
CHECK	ED	APPROVED	D3531	REV. A SHEET 1 OF 3
DATÉ	06.0	06.21	BRACKET ASSEMBLY	SCALE 1:2
Α	0	6.06.21	NEW ISSUE	

UNDER REVIEW














D3531-041 BRACKET ASSEMBLY

PARTS LIST

NOTE:

FINISH: POWDER COAT ASSEMBLY BLACK SANDTEX (4.3.5.7) PER DART QSI 005 4.3 ALL PARTS

QTY.	P/N	DESCRIPTION
Χ	D3531-041	BRACKET ASSEMBLY
1	D3531-1	BRACKET
1	D3531-3	BRACKET FRONT PLATE
12	MS20470AD4-4	RIVETS

COPYRIGHT © 2006 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

